# Cargotec

# **Supplier Requirements**

1 Management Responsibility	7
1.1 Business Plan	7
1.2 Key Performance Indicators	7
1.3 Financial Stability	7
1.4 Quality Management System	7
1.5 Environmental Management System	7
1.6 Management Review	7
1.7 Resources	7
1.8 Fair Competition	8
1.9 Whistle-blower policy	8
1.10 Code of Conduct	8
1.11 Conflict of Interest & Sanctioned or Exposed Individuals	8
2 Quality Management	9
2.1 Document Control	9
2.2 Quality Planning	9
2.3 Internal Audits	9
3 Environmental	10
3.1 Environmental matters	10
3.2 Material data sheets	10
3.3 International Material Data System (IMDS) Registration	10
3.4 REACH/ EPA Compliance	10
3.5 Environmental impacts	10
3.6 Carbon Emission Reductions	10
4 Risk Management	11
4.1 Risk Plan	11

2022-01-20	Rev.4

4.2 Compliance with Legislation	11
4.3 Contingency Plan	11
4.4 Emergency Procedures	11
4.5 Security	11
4.6 Insurance	11
4.7 Confidentiality Agreement	12
5 Project Management	13
5.1 Contract Review	13
5.2 Project Management planning	13
5.3 Resources and Contact person	13
5.4 Escalation process for Project Management	13
5.5 Change Management	13
5.6 Revision Control	13
5.7 IPR - Intellectual Property rights	13
5.8 Project Management handover	13
5.9 Prototype building	14
6 Health and Safety Management	15
6.1 Health and Safety Management system	15
6.2 Eliminating hazards and reducing Health and Safety risks	15
6.3 Incidents reporting and investigation	15
7 Production	16
7.1 Process Flow Chart	16
7.2 Customer Approval	16
7.3 Work Instructions	16
7.4 Maintenance	16
7.5 Customer Tooling	16
7.6 Control Plan	16
7.7 Continues Improvements	16
7.8 Rework	16
7.9 Root Cause Analyses	17
7.10 Releasing of Products	17
7.11 Measuring Equipment	17
7.12 Calibration of measuring equipment	17
7.13 Incoming Inspection	17

		HIAB • KALMAR • MACGREGOR	
2022-01-20 Rev.4			

7.14 Managing Transportation	17
7.15 Layout and Material Flow	17
7.16 Product Audit	17
7.17 Labelling and Quantity delivery	17
7.18 Identification	18
7.19 Traceability	18
8 People and their Development	19
8.1 Human rights, child labor, forced labor	19
8.2 Compensation and working time	19
8.3 Right to organize	19
8.4 Equal Opportunities to grow	19
8.5 Education of Personal	19
8.6 Competence Matrix	19
8.7 Development Plans for Employees	19
9 Product Development	20
9.1 Product Development process	20
9.2 Design requirements	20
9.3 Project planning	20
9.4 Design Review	20
9.5 Development Tools	20
9.6 Control of Design Changes	20
9.7 R&D Capabilities & Innovation	20
9.8 Prototype building	20
9.9 QA of Prototypes,	21
10 Purchasing (Supply Chain Management)	22
10.1 Supplier Selection	22
10.2 Supplier Monitoring	22
10.3 Supplier Code of Conduct	22
10.4 Source Identification	22
10.5 Outsourced Services	22
10.6 Outsourced & Assigned Products	22
11 Continuous Improvement	23
11.1 Continuous Improvement Program	23
12 Warranty	24

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

12.1 Warranty issues	24
12.2 Warranty Claims	24
13 Product Liabilities	25
13.1 Recall Procedure	25
14 Logistic	26
14.1 Logistic support	26
14.2 Integrated Planning System	26
14.3 Materials management	26
14.4 Capacity planning	26
15 Spare Parts	27
15.1 Quality	27

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# 1 Management Responsibility

#### 1.1 Business Plan

The Supplier shall have a clear business plan and a strategy to guide the future development of the company. This plan shall be reflected in respective plans of business units, functions or equal. The plan shall include objectives, targets, actions, responsibilities and schedules.

#### **1.2 Key Performance Indicators**

The Supplier shall define key performance indicators for SQDEC (Sustainability- including Social part, Safety and environment, Quality as PPM, Deliveries, Environmental and Cost) as minimum, which will be used to monitor the company's performance towards its strategic objectives. These KPI shall be measurable towards the targets into the Business plan. Management shall review these indicators on a regular basis and use the data to initiate improvement actions.

#### **1.3 Financial Stability**

The Supplier shall demonstrate a solid financial history.

#### 1.4 Quality Management System

The Supplier shall ensure that the Supplier itself and all its production units minimum are certified according to ISO 9001

#### 1.5 Environmental Management System

The Supplier shall ensure that the Supplier itself and all its production units minimum are working according to requirements of ISO 14001.

#### **1.6 Management Review**

Management shall ensure the quality, environmental and risk management systems' applicability and effectiveness by regular reviews. The reviews shall lead to planning and implementing improvements.

#### 1.7 Resources

Suppliers Management shall ensure availability of adequate resources. Employees shall have the required education, training and competencies for their position and tasks. The supplier shall create and retain all Certificates, These development plans shall support the fulfilment of the supplier's business plan.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

#### **1.8 Fair Competition**

The Supplier deals fairly with individuals and entities with whom they interact.

#### **1.9 Whistle-blower policy**

The supplier has a whistle-blower policy that allows people that wish to report gross negligence or intended breaches with legislation/ethics to report anonymously without the threat of losing their employment or career options

#### 1.10 Code of Conduct

The Supplier shall have a documented code of ethics or a code of conduct implemented, including temporary employees that are in line with Cargotec Supplier Code of Conduct.

#### 1.11 Conflict of Interest & Sanctioned or Exposed Individuals

The supplier shall if they have former or current Cargotec Employees working in or owning the company, or relatives working at Cargotec, be open and transparent of their position in the company. The supplier shall if they have sanctioned individuals or PEP's (Politically exposed person) working in or owning the company, be open and transparent of their position in the company.

		HIAB • KALMAR • MACGREGOR	
2022-01-20 Rev.4			

# 2 Quality Management

# 2.1 Document Control

The Supplier shall have a document control system to create, check, approve, release, distribute and delete quality system related documentation and data throughout the whole organization.

# 2.2 Quality Planning

The Supplier shall have a systematic Quality project planning process.

It shall be used to determine if all engineering design records and specification requirements are properly understood by the supplier. The manufacturing process shall have the potential to produce products consistently meeting these requirements on time.

## 2.3 Internal Audits

The Supplier shall conduct internal quality (System, Project and Process) audits using qualified auditors according to set procedures. Internal quality audits shall be planned and executed according to the plans. Audit results shall be a subject to regular reviews and respective corrective actions shall be taken without unnecessary delay. These corrective actions' effectiveness shall be verified.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# 3 Environmental

#### **3.1 Environmental matters**

The Supplier shall consider environmental matters during all phases of its product development process. All reasonable efforts shall be made to eliminate or reduce hazardous contents from the product and its manufacturing process.

#### 3.2 Material data sheets

The Supplier shall have procedures for and evidence of recording the raw material content of its products, Certificates and material data sheets.

#### 3.3 International Material Data System (IMDS) Registration

When requested by Cargotec, the supplier shall obtain adequate knowledge and report material data into IMDS.

#### 3.4 REACH/ EPA Compliance

Supplier shall at all times provide documented compliance to REACH (Registration, Evaluation, Authorization and Restriction of Chemicals) on Substances of Concern and any other legislation valid for its product, like EPA restrictions in the US -prohibitions on processing and distribution of Phenol, Isopropylated Phosphate (3:1) (PIP (3:1)) or RoHS

#### 3.5 Environmental impacts

The Supplier shall identify environmental impacts. It shall include, but not limited to, emissions to air, water and soil. All impacts shall be monitored for continuous improvements.

#### 3.6 Carbon Emission Reductions

Supplier should have clear understanding of own CO2 emissions: scope 1 (direct- fuel combustion/ own vehicles)/ scope 2 (indirect - electricity purchased) / scope 3 (upstream - supply chain/ downstream - product use and end of life), and clear strategy with projects defined and running, aiming significant reductions of CO2 emissions.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# 4 Risk Management

# 4.1 Risk Plan

The Supplier shall have an up to date risk plan. It shall promote effective identification, analysis, control, prevention and monitoring of business risks. Management shall ensure that it is appropriately communicated, understood and implemented throughout the whole organization. The plan shall include strategy, financials, quality, operations, supply, logistics, technology, location, natural hazards (incl. pandemic) and (trade) political risks.

## 4.2 Compliance with Legislation

Supplier must provide documented compliance of National and International legislations as well as specific European Union legislations. Supplier must also continuously remain updated of changes and news to the legislation.

# 4.3 Contingency Plan

Supplier shall have a Business contingency plan. Including Major disruptions, Fire, Production stop etc. It shall guarantee business operations continuity and customer service in case of an interruption

## 4.4 Emergency Procedures

The Supplier shall have appropriate emergency procedures including evacuation and rescue plans.

#### 4.5 Security

The Supplier shall implement security procedures covering buildings, employees, documents, IT systems and movement of products. It shall also include measures to prevent unauthorized access to its IT systems. Necessary precautions shall be implemented in form of fireproof cabinets, virus scans, up-to-date electronic back-ups etc. Supplier should maintain restricted access to packing and warehouse (supply chain security)

#### 4.6 Insurance

The Supplier shall have insurance coverage (or similar arrangement in its own capital) that allows it to recover from major disruptions. The Supplier shall have: a liability insurance for finished products covering Cargotec's market areas.

## 4.7 Confidentiality Agreement

The Supplier shall have a confidentiality agreement with all of its employees who have access to sensitive company or customer information or technology, including temporary employees and resident subcontractors.

		HIAB - KALMAR - MACGREGOR
2022-01-20 Rev.4		

# **5 Project Management**

#### 5.1 Contract Review

The Supplier shall have a formal Project management review system to convert customer requirements into Supplier's internal requirements. The requirements referred to may be: Requirements specifically documented in Cargotec specifications, purchase order, agreement, request for quotation or other documentation

#### 5.2 Project Management planning

The supplier shall have a project plan for its project management, with milestones included. The plan shall cover important activities from RFQ to start of production.

#### 5.3 Resources and Contact person

The supplier shall make sure that they have the right resources available for Project management, including their responsibility. The supplier shall nominate contact person(s) to manage the relationship between Cargotec and the Supplier. The contact persons shall have fluent skills in English.

#### 5.4 Escalation process for Project Management

The supplier shall have a defined process for handling disruptions in the project plan, and inform Cargotec if time plan will be affected.

#### 5.5 Change Management

Contractual changes like engineering changes and changes related to customer requirements shall be managed using Project Management Planning.

#### **5.6 Revision Control**

The supplier shall have a system to manage and control that the right specification revisions (such as drawings) are used for manufacturing. It must also include sub suppliers (Tier 2).

#### 5.7 IPR - Intellectual Property rights

The supplier shall have a policy or procedure to protect 3rd party IPR (Intellectual Property Rights). According to the policy the Supplier shall have a procedure within its Project Management system to assure that no 3rd party IPR are included in deliveries to Cargotec without the right to do so.

#### 5.8 Project Management handover

The supplier shall have an official handover process from project management to serial production. There shall be an agreement between the project and production that they are ready to start serial production.

		HIAB • KALMAR • MACGREGOR	
2022-01-20 Rev.4			

# 5.9 Prototype building

Prototypes shall be managed early in the supplier's project management system. The plan shall clearly define how and when a prototype shall be built.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

## 6 Health and Safety Management

#### 6.1 Health and Safety Management system

The Supplier shall have a documented Health and Safety management system. It shall be under regular reviews and emphasize continuous improvement actions.

#### 6.2 Eliminating hazards and reducing Health and Safety risks

The Supplier shall have a process for Health and Safety precautions and hazard identification, risk assessment, elimination of hazards and reduce all significant HS risks.

#### 6.3 Incidents reporting and investigation

The supplier shall have a procedure/ process in place, including reporting, investigating and taking action to determine and manage incidents.

		HIAB • KALMAR • MACGREGOR	
2022-01-20 Rev.4			

# **7 Production**

#### 7.1 Process Flow Chart

The supplier shall have a production process implemented according to an optimized plan. The process flow shall ensure effective operation and control of the process. If any part of the process is subcontracted, this shall be indicated in the process flow.

#### 7.2 Customer Approval

The supplier's process and materials including related changes shall be qualified and approved according to set procedures by the Customer. The records of process and material qualification shall be available to the Customer.

#### 7.3 Work Instructions

The Supplier shall have work instructions, it shall include descriptions for each workstation in the process.

#### 7.4 Maintenance

The Supplier's process equipment shall be qualified for the purpose. The equipment shall be under preventive maintenance according to a specific plan. All records of maintenance shall be stored.

#### 7.5 Customer Tooling

The supplier shall establish appropriate procedures for storing, inspecting and maintaining customer owned tools, fixtures and jigs. All customers owned equipment must be labelled with "property of Cargotec".

#### 7.6 Control Plan

The supplier shall define a production control plan in order to keep the process under control. Respective controls shall be established, for processing, assembly and inspection/testing with results recorded. The control plan shall be available at the different workplaces. All inspections, testing according to control plan have been conducted and all records maintained and stored. Operators shall have been trained..

#### 7.7 Continues Improvements

The Supplier shall use statistical methods and techniques to analyze process data for continuous improvement. All records of all improvements must be stored.

#### 7.8 Rework

The supplier shall define in-process rework and appropriate procedures for conducting it. Repaired and/or reworked products shall be re-inspected.

		HIAB • KALMAR • MACGREGOR	
2022-01-20 Rev.4			

#### 7.9 Root Cause Analyses

The supplier must conduct root cause analyses for production and process failures. All records must be stored.

#### 7.10 Releasing of Products

Prior to releasing products for delivery the Supplier shall assure that the products conform to requirements.

#### 7.11 Measuring Equipment

The serial production supplier shall have all necessary measuring equipment to be able to measure and verify if the products comply with all customer requirements, stated on drawings and standards. And also to be able to keep an in-house process control.

#### 7.12 Calibration of measuring equipment

The Supplier shall have a documented procedure for the calibration and certification of tools/equipment. All data from calibration and certification of inspection, measurement and test equipment must be stored.

#### 7.13 Incoming Inspection

The Supplier shall have a procedure describing appropriate inspection of incoming materials. These procedures shall include systems to ensure traceability of product if found unacceptable.

#### 7.14 Managing Transportation

The Supplier shall establish methods and means for preventing damage to materials and products during handling and transportation.

#### 7.15 Layout and Material Flow

The Supplier's manufacturing, "end to end" shall have a clear layout to avoid bottlenecks created due to space constraints or unsuitable material or product flows. Well-organized, clean and proper order.

#### 7.16 Product Audit

The Supplier shall conduct Product Audits at suitable intervals of the products while they are in stock.

#### 7.17 Labelling and Quantity delivery

The Supplier shall pack and label the products appropriately prior to the delivery to avoid damage or loss. It shall also be established controls and procedures to assure on-time and right quantity deliveries.

#### 7.18 Identification

The Supplier shall have a documented procedure for ensuring that all products are identified to indicate their conformance or non-conformance throughout all process steps

		HIAB - KALMAR - MACGREGOR	
2022-01-20 Rev.4			

# 7.19 Traceability

The Supplier shall implement a method for traceability of individual parts used in the final product throughout all stages of the manufacturing process. When traceability of a finished product is a specific requirement, every completed product or lot shall have a clear, well-documented means of identification. This identification shall be recorded and retained as a quality record.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# 8 People and their Development

#### 8.1 Human rights, child labor, forced labor

The Supplier does not breach human rights at any of their work places, nor does it allow child labour and forced labour.

#### 8.2 Compensation and working time

Compensation paid to workers and working time is in line with legal requirement and international standards (ILO= International Labor Organisation)

#### 8.3 Right to organize

The Employees have a right to organise themselves to bargain employment conditions.

#### 8.4 Equal Opportunities to grow

The Employees have opportunities independent of race, gender, association, nationality, to grow towards other and more senior positions.

#### 8.5 Education of Personal

The supplier shall continuously educate and train their personal/resources. All records of all training must be stored.

#### 8.6 Competence Matrix

The supplier shall have a procedure in place to define/monitor the competence skills the employees/resources possess.

#### 8.7 Development Plans for Employees

The supplier shall regularly conduct Personal Development Plans with all their employees.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# **9 Product Development**

#### 9.1 Product Development process

The Supplier shall have a documented product development process to ensure effective planning, execution and control of the product throughout its lifecycle.

#### 9.2 Design requirements

The development process shall be based on the requirements identified during contract review.

#### 9.3 Project planning

The supplier shall have a project planning tool. It shall clearly identify responsibility for engineering/design and development. Project shall be managed according to planned targets in terms of resourcing, scheduling, product quality and costs.

#### 9.4 Design Review

The Supplier shall perform formal design reviews to systematically analyze the progress of the product development activities and their output at certain milestones.

#### 9.5 Development Tools

The Supplier shall validate all design and development tools including software. The tools used shall be compatible with ones used by Cargotec.

#### 9.6 Control of Design Changes

The Supplier shall establish procedures to manage track and document changes in requirements and designs. The process shall include practices for documentation and version management. The Supplier shall inform Cargotec of all engineering changes.

#### 9.7 R&D Capabilities & Innovation

The supplier shall have a strategy and plan for future technologies and innovation.

#### 9.8 Prototype building

The Supplier shall be able to handle prototype building during the project phase in the project management. Prototypes shall be provided to customer according to a set time plan and effective manner.

#### 9.9 QA of Prototypes,

The supplier must verify that prototypes are produced so they are representing the technical documentation. Records of verification must be available upon request.

		HIAB • KALMAR • MACGREGOR	
2022-01-20 Rev.4			

# 10 Purchasing (Supply Chain Management)

#### **10.1 Supplier Selection**

The Supplier shall have a defined process to select and approve its new potential suppliers, including Code of Conduct compliance.

## **10.2 Supplier Monitoring**

Supplier performance shall be monitored on monthly (serial production) basis on minimum QD (Quality and Deliveries) and targets shall be defined.

#### **10.3 Supplier Code of Conduct**

The supplier requires their existing suppliers to sign a Code of Conduct (or similar process, to verify sustainability and compliance in their supply chain).

#### **10.4 Source Identification**

The supplier commits to provide necessary information to confirm that conflict minerals (tantalum, tin, tungsten, and gold) in their supply-chain are "conflict free". The supplier are following the OECD due diligence guideline for Responsible Supply Chains of Minerals from Conflict-Affected and High-Risk Areas.

#### **10.5 Outsourced Services**

The supplier shall have procedures to ensure quality and sustainability of outsourced services (example of IT).

#### **10.6 Outsourced & Assigned Products**

The supplier shall have a procedure for Quality Planning and Assurance of outsourced and assigned products (example of painting).

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# **11 Continuous Improvement**

# 11.1 Continuous Improvement Program

The supplier shall have continuous improvement programs. The programs shall be applicable for internal improvements, as well as for supply chain improvements.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# 12 Warranty

#### 12.1 Warranty issues

The supplier shall have a process for handling Warranty issues.

## 2.2 Warranty Claims

The Supplier shall have a corrective action process for warranty to evaluate customer claims

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# **13 Product Liabilities**

#### 13.1 Recall Procedure

The Supplier shall have a Product Liability Procedure including a recall process and defined liability related responsibilities.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# 14 Logistic

#### 14.1 Logistic support

The Supplier shall have an established system and access to necessary service providers to supply both production material and spare parts to Cargotec on a global basis

#### 14.2 Integrated Planning System

The Supplier should use an integrated planning system for order management, materials requirements planning, procurement, warehousing and inventory management. In order to reduce the administrative waste in his processes, supplier should have an adequate Electronic Data Interchange (EDI) system in place.

#### 14.3 Materials management

The Supplier shall work according to First-In-First-Out (FIFO) principle. The Supplier should actively manage inventory accuracy by regularly stock takes.

#### 14.4 Capacity planning

The Supplier shall have a tool for capacity planning. This tool must also include sub-suppliers, sub-contractors and raw-materials.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		

# 15 Spare Parts

# 15.1 Quality

The supplier shall have a process for Quality Planning and Assurance of spare parts.

		HIAB • KALMAR • MACGREGOR
2022-01-20 Rev.4		